

MARKED UP VERSION OF ALL AMENDED CLAIMS

14. (Amended) A motor-driven pump unit[, in particular] for antilock brake systems of motor vehicles[,] comprising:

an electric motor that is arranged on one side of a pump unit and fastened thereto,
an electronic unit that is arranged on another side of the pump unit and fastened thereto,

means for mounting carbon brushes in an axially movable manner and means for the electric contacting of the carbon brushes in connection with the axial installation of the unit.

15. (Amended) A motor-driven pump unit according to Claim 14, wherein the mounting means is arranged in the pump unit [at the level of the pump housing].


FEE DEFICIENCY

NOTE: If there is a fee deficiency and there is no authorization to charge an account, additional fees are necessary to cover the additional time consumed in making up the original deficiency. If the maximum, six-month period has expired before the deficiency is noted and corrected, the application is held abandoned. In those instances where authorization to charge is included, processing delays are encountered in returning the papers to the PTO Finance Branch in order to apply these charges prior to action on the cases. Authorization to charge the deposit account for any fee deficiency should be checked. See the Notice of April 7, 1986, (1065 O.G. 31-33).

6. ☒ If any additional extension and/or fee is required, charge Account No. 18-0013

AND/OR

☒ If any additional fee for claims is required, charge Account No. 18-0013


SIGNATURE OF PRACTITIONER

Reg. No. 45,184

Christopher J. Voci
(type or print name of practitioner)

Tel. No. 248-594-0648

39533 Woodward Ave., Suite 140
Bloomfield Hills, MI 48304

CUSTOMER NO.: 010291